No. of printed pages: 2

46]

SARDAR PATEL UNIVERSITY

M.Sc. (Polymer Science & Technology), Semester- II Examination-2018 Tuesday, 10th April, 2018 10:00 A.M. to 1:00 P.M. PS02CPST21: Polymer Characterization Total Marks: 70 Note: (1) Attempt all questions. (2) Figures to the right indicate full marks. Q.1 Write appropriate choice for the following. (08)Rockwell hardness test is ASTM D _____. (1) (i) 783 (ii) 784 (iii) 785 (iv) 786. (2) can affects batch to batch variation in polymerization process. (i) Temperature (ii) Purity of monomer (iii) Time (iv) All of above. An alternate method for measuring solvent stress cracking employs a (3)specimen of size inch. (i) 1.5×0.5 (ii) $4\times1\times0.03$ (iii) $4\times2\times0.03$ (iv) 1.5×2 . Volume resistivity = _____. $(i)\,\frac{A}{t(R_{\nu})}\,\,(ii)\,\frac{At}{\rho(R_{\nu})}\,(iii)\,\frac{A}{t(\pi R_{\nu})}\,\,(iv)\,\frac{At(R_{\nu})}{\omega}\,.$ can be used as heating media in softening point measurement (5)techniques. (i) Glycerol (ii) Paraffin oil (iii) Silicon oil (iv) All. $\overline{M_n}$ is determined by . (6) (i) GPC (ii) HSMO (iii) VPO (iv) all of above. Polytetrafluoroethylene is highly chemical resistant because of (i) high crystalline structure (ii) lack of branching (iii) strong bond of C-F (iv) all of above. Dielectric strength is expressed as (i) volts per thickness (ii) thickness per volts (iii) volts per temperature (iv) none of above. Q.2Attempt any seven of the following (14)(1)Define gel time and peak exotherm temperature of thermosetting resin. Differentiate between testing conditions and conditioning of test specimen. **(2)** Explain different classes of polymers on the basis of inherent flammability. (3) (4) Define hardness. Explain factors affecting hardness test.

Enlist requirements of plastic for effective insulator. **(5)**

	(6)	Explain stress – strain plot for the polymer materials having different nature.	
	(7)	Write down the significance of material characterization.	
	(8)	What do you mean by dissipation factor? Explain.	
	(9)	How does thermoplastic polymers resist to sulphide staining? Explain.	
Q.3	(a)	Explain in detail about gel permeation chromatography (GPC) technique.	(06)
	(b)	Discuss in detail about vapour phase osmometry (VPO).	(06)
		OR	
	(b)	Write a note on following.	(06)
		1. High speed membrane osmometry.	
		2. Sedimentation velocity method.	
Q.4	(a)	Discuss in detail about density gradient test for thermoplastic polymer.	(06)
	(b)	Explain following.	(06)
		1. Vicat softening point.	
		2. Bubble and Brookefield viscometer.	
		OR	
	(b)	Explain following.	(06)
		1. Ring and ball method.	
		2. Heat deflection temperature method.	
Q.5	(a)	What do you mean by tensile test? Discuss in detail about test procedure and	(06)
		factors affecting test results.	
	(b)	Explain following impact test.	(06)
		1. Izod test.	
		2. Falling weight test.	
		OR	
	(b)	Describe in detail about low oxygen index test. Explain factors affecting test	(06)
		results.	
Q.6	(a)	What is dielectric strength of thermoplastics material? Explain detailed	(06)
		measurement procedure, diagram and factors affecting test results.	
	(b)	Write a note on environmental stress cracking resistance test.	(06)
		OR	
	(b)	What is solvent stress cracking resistance of polymers? Explain test	(06)
		procedure with neat labelled diagram.	
